






I = Inspected NI = Not Inspected NP = Not Present R = Repair Needed D = Defective					
					Item
I	NI	NP	R	D	Item
					Comments
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Doors Some interior doors to both bedrooms were too long. Doors were actually touching carpet. Each room had a forced hot air heater vent but no return. See discussion below for additional details.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Windows No problems found
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Walls No problems found
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Ceilings No problems found
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Floors No problems found
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Interior living spaces Smoke detectors <b>Smoke detector in downstairs room had been removed. Recommend that detector be replaced for proper safety. Reference picture CIMG3545.</b>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Attachments No problems found
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Cabinets and Trim No problems found
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Window treatments
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior living spaces Locks

**Photos and Additional Comments**

Interior Living Spaces: With the doors touching the carpet, and if they are closed, this creates a situation where air cannot circulate through the room. Hot air from the furnace will fill the room until pressure builds up and then air will significantly decrease. The cold air is not permitted to circulate under the door to the cold air return. Proper air circulation is important for proper room ventilation. Reference picture CIMG3778.