

| I = Inspected NI = Not Inspected NP = Not Present R = Repair Needed D = Defective | | | | | | |
|-----------------------------------------------------------------------------------|--------------------------|--------------------------|-------------------------------------|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| I | NI | NP | R | D | Item Comments | Condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Siding | Acceptable |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Fascia, soffits, trim Door casing has been hit with vehicle and has been knocked slightly out of alignment. Reference Pictures: CIMG4171 | Damaged but operational |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Service Door(s) | Acceptable |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Window(s) | |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overhead door(s) All safety features of the door functioned as designed. | Acceptable |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Safety eye(s) No problems. Safety eyes worked fine and stopped door when beam was interrupted. | Functional |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Water faucets | |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Window wells, crawl space vents | |

Photos and Additional Comments

Trim: Functional, but junction between bricks and door casing should be resealed.